

Oil Field Environmental Incident Summary

Incident: 20140705184348 **Date/Time of Notice:** 07/05/2014 18:43

Responsible Party: T & R Transport

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: VAUGHN BECKY 5501 11-1B

Field Name: COW CREEK

Well File #: 25769

Date Incident: 7/5/2014 **Time Incident:** 09:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 101

Sec: 1

Qtr: LO T4

Location Description: Spill occurred in ditch east of highway 2 on 62nd street approximately 2 miles east on north side of road in road ditch.

Submitted By: Jason Keller

Received By:

Contact Person: Jason Keller
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 3 Mile

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	50	Barrels	30	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Immediate risk was to topsoil contamination, all excavated and replaced with fresh topsoil.

Areal Extent:

Potential Environmental Impacts:

Topsoil contamination.

Action Taken or Planned:

Leaked brine water was sucked up and contaminated topsoil was excavated and fresh topsoil was placed.

Wastes Disposal Location: Waste will be disposed of at Secure 13 mile solid waste disposal.

Agencies Involved: Local Fire Department Local Law Enforcement

Updates

Date: 7/6/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release containment is consistent with the wording elsewhere in the report. Followup is necessary to determine containment and cleanup.

Date: 7/9/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/9/2014 at 13:36, on location. Location description accurate. Wellpad location incorrect, and actual wellpad location is not near incident area anyway. Area in ditch impacted by brine spill has been scraped up and replaced with new topsoil. Electrical conductivity readings show background readings are in the 2-3 mS range. Within area scraped and replaced with new soil, EC readings are all below 1 mS. However, where scraped area stops on its western side, there is noticeable dead vegetation surrounded by green vegetation. EC readings within this dead vegetation show:

3" = 15.6 mS

6" = 10.5 mS

*hit rocks/gravel

Area of dead vegetation is approximately 10' long by 2' wide.

Called report contact and communicated findings and need to extend area scraped and replaced to the west. Report contact will plan to have crews out on Friday to clean the remaining impact. Report contact will notify NDDoH once cleanup is complete.

Date: 7/11/2014 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call from report contact. According to contact, area scraped has been extended to take care of remaining impact in ditch.

Date: 9/16/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

9/16/2014 at 10:10, on location. Scraped area in ditch has been extended to area previously noted as having visibly impacted vegetation. No visible impact to vegetation outside of scraped area. New vegetation is starting to grow in scraped area.